

Reference

Repairing the Retaining Wall-Repairs made after a landslide due to Typhoon Xangsane,

Location: Taipei, Taiwan/ Client: Geotechnical Engineering Office, Public Works Department, Taipei City Government / 2000

Under construction



Still working after 20 years, recorded on March, 2021






Hualien & Taitung Coastal Highway

Location: East coast of Taiwan/ Client: The Directorate General of Highways/ 2006

Under construction







Water and soil conservation project on the east side of Toad Hill Settlement

Location: Taipei, Taiwan/

Client: Geotechnical Engineering Office, Public Works Department, Taipei City Government/

2019





Taoyuan International Airport

Location: Taoyuan, Taiwan/ Client: Civil Aeronautics Administration, Ministry of Transportation and Communications/ 2006

Under Construction









Taipei Songshan Airport

Location: Taipei, Taiwan/ Client: Civil Aeronautics Administration, Ministry of Transportation and Communications/ 2019

Under Construction








Taipei Songshan Airport-Sidewalk

Location: Taipei, Taiwan/ Client: Civil Aeronautics Administration, Ministry of Transportation and Communications/ 2019






Jinan Railway

Location: Jinan, China/ Client: Ministry of Railways of China

Under Construction



Filtered Water after Drainbelt






TK128 HSR Railway side drainage

Location: Miaoli, Taiwan/ Client: Taiwan High Speed Rail Corporation/ 2022

As it is still under construction, please do not publish this page







Taichung Station

Location: Taichung, Taiwan/ Client: Taiwan Railways Administration/ 2016

Under Construction









RETAINING WALL OF "TAWULOON" HIGHWAY 西滨公路大武仓股加劲挡土砦



BOTTOM VIEW OF THE WALL 加劲挡土墙底部基础



DRILLING OPERATION 底部钻孔作业

Testing site for comparison under highway foundation in northern Taiwan



Retaining wall drainage system for school yard in central Taiwan











